

Current AVN-230* Flight Inspection Orders and Notices as of 5/15/98
--

The orders and notices listed in this section may now be accessed on the Internet. The address is:
<http://www.mmac.jccbi.gov/avn/download.html>

<u>Order</u>	<u>Issue Date</u>	<u>Title</u>
8200.1A	5/22/96	United States Standard Flight Inspection Manual
Chg 1	9/2/97	Effective 10/15/97
VN 8200.3	2/13/98	Policy With Respect to Military Program Procedures for Flight Inspection of Foreign-Owned Air Navigation Facilities
8200.32	3/21/89	Flight Inspection Criteria For Aspen, Colorado Localizer Type Directional Aid (LDA)
8200.32 Chg 1	7/22/96	
8240.36F	9/3/97	Instructions for Flight Inspection Reporting
		Effective 10/15/97
8240.47B	11/12/96	Determination of ILS Glidepath Angle, RDH, and GPI
8240.47B Chg 1	03/18/97	
<u>Notice</u>	<u>Issue Date</u>	<u>Title</u>
N8200.66	10/9/97	Change in Order 8200.1A, Change 1, United States Standard Flight Inspection Manual, and Order 8240.36F, Instructions for Flight Inspection Reporting
N8200.67	2/20/98	Change in Order 8200.1A, Change 1, United States Standard Flight Inspection Manual, and Order 8240.36F, Instructions for Flight Inspection Reporting
N8240.33	2/20/98	Change in Order 8240.47B, Determination of Instrument Landing System (ILS) Glidepath Angle, Reference Datum Heights (RDH), and Ground Point of Intercept (GPI)
N 8240.34	4/27/98	Change in Order 8240.47B, Determination of Instrument Landing System (ILS) Glidepath Angle, Reference Datum Heights (RDH), and Ground Point of Intercept (GPI)
N 8200.68	5/7/98	Change in Order 8200.32, Flight Inspection Criteria for Aspen, Colorado, Localizer Type Directional Aid (LDA)

Cancellation of AVN-230* Flight Inspection Orders and Notices
--

<u>Order/Notice</u>	<u>Cancel Date</u>	<u>Title</u>
8200.24A	2/98	Policy with Respect to Flight Inspection of Air Navigation Facilities in Foreign Territory
8240.36E	10/15/97	Instructions for Flight Inspection Reporting
8240.39A	2/98	Operational Procedures for the Automated Flight Inspection System (AFIS)
N8200.64	10/15/97	Corrections to Order 8200.1A, United States Standard Flight Inspection Manual
N8200.65	10/15/97	VORTAC Tolerances
N8240.30	10/15/97	Change in Order 8240.36E, Instructions for Flight Inspection Reporting
N8240.31	10/15/97	Change in Order 8240.36E, Instructions for Flight Inspection Reporting
N8240.32	2/20/98	Change in Order 8240.47B, Determination of Instrument Landing (ILS) Glidepath Angle, Reference Datum Heights (RDH), and Ground Point of Intercept (GPI)

* Please note that this listing includes only those flight inspection directives for which the Flight Inspection Policy and Standards Branch (AVN-230) is responsible. This list does not encompass all flight inspection directives.

Shaded areas indicate changes since previous listing.